Kathleen Clarke

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor Do Box 145801

Salt Lake City, Utah 84114-5801

Executive Director
Lowell P. Braxton
Division Director

Executive Director

801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

INSPECTION REPORT

Partial:	Com	plete: XXX	Explo	ration:	
Inspection Date &			_		
=		ection: 10/			

Mine Name: <u>Deer Creek Mine</u> County: <u>Emery</u> Permit Number: <u>C/015/018</u>	
ermittee and/or Operator's Name: PacifiCorp	
Business Address: P.O. Box 310, Huntington, Utah 84528	
Type of Mining Activity: Underground XXX Surface Prep. Plant Other	
Company Official(s): <u>Dennis Oakley</u>	
state Official(s): Stephen J. Demczak Federal Official(s): None	
Veather Conditions: Cooled, 30's	
Existing Acreage: Permitted 18,866 Disturbed 95.79 Regraded Seeded Seeded	
Status: Active XXX	

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	$\overline{\Box}$	[X]	Ш
2.	SIGNS AND MARKERS	<u>[X]</u>	$\overline{\Box}$	[X]	
3.	TOPSOIL	<u>[X]</u>	$\overline{\Box}$	[X]	П
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	\Box	[X]	П
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	$\overline{\Box}$	[X]	П
	c. OTHER SEDIMENT CONTROL MEASURES	[X]	\Box	[X]	\Box
	d. WATER MONITORING	[X]	\Box	[X]	П
	e. EFFLUENT LIMITATIONS	[X]	\Box	[X]	\Box
5.	EXPLOSIVES	[X]	\Box	\Box	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]	\Box	\Box	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	\Box	[X]	\Box
8.	NONCOAL WASTE	[X]	\Box	[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	[X]	\Box	\Box	\Box
10.	SLIDES AND OTHER DAMAGE	[X]	П	\Box	\Box
11.	CONTEMPORANEOUS RECLAMATION	[X]	\Box	\Box	\Box
12.	BACKFILLING AND GRADING	[X]	\Box		\Box
13.	REVEGETATION	[X]	\Box		П
14.	SUBSIDENCE CONTROL	[X]	\Box	\Box	\Box
15.	CESSATION OF OPERATIONS	[X]	\Box	\Box	\Box
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	\Box	П	\Box
	b. DRAINAGE CONTROLS	[X]	\Box		\Box
17.	OTHER TRANSPORTATION FACILITIES	[X]	Ш	\Box	\Box
	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	\Box	[X]	\Box
19.	AVS CHECK (4th Quarter- April, May, June)	[X]	\Box		П
20.	AIR QUALITY PERMIT	[X]		П	· []
21.	BONDING & INSURANCE	[X]	П	[X]	

OL

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/015/018



(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The Mill Fork significant revision was received by the Division on 10/29/2001. The permittee is in the process of evaluating the relocation of the non-coal waste storage site at the Deer Creek Mine. If this relocation is approved by management of Energy West, this would require an amendment being submitted to the Division.

- -The DOGM permit expires 02/07/2006.
- -Certificate of Insurance Policy # U0614A00 terminates 04/01/2002. Coverage is by Assoc. Elec. & Gas Ins. SVSC LTD.
- -Reclamation agreement is dated December 11, 2000. The bonding amount is \$3,000,000. The operator's copy of the reclamation agreement is not signed by the Division, only by the Operator. Told the Operator that they need to request a signed copy from the Division and keep it on file.
- -UPDES permit UT0023604 expires 11/30/2002.
- -Air Quality Permit NO. DAQE-926-96 issued 10/04/1996 allows for 4,500,000 tons per 12 month period. A second permit is for the waste rock site DAQE-926-91.

2. SIGNS AND MARKERS

The ID sign is in place. Other markers, as required by the coal rules, are in place.

3. TOPSOIL

The topsoil piles were spot-checked with no signs of erosion. The Deer Creek Mine topsoil piles are located at Rilda Canyon and the coal refuse site.

4A. HYDROLOGIC BALANCE: DIVERSIONS

Several diversions were spot-checked and complied with the R645 Coal Rules. No water was flowing during the inspection.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The mine site's sediment pond was inspected with no hazardous conditions noticed. The pond was discharging during the inspection.

The sediment ponds were inspected by P. E. John Christensen, badge number 165651, on September 7, 2001.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Sediment control measures along the belt line were inspected and it appeared they would function if an event occurred.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: <u>C/015/018</u>



4D. HYDROLOGIC BALANCE: WATER MONITORING

The second quarter water monitoring report was reviewed at the mine office and the electronic water data system was used at the Price Field Office. The Electronic Data System needs to reflect the required parameters in the Mining and Reclamation Plan. Presently, the Electronic Data System shows a complete suite of parameters. This information has been relayed to the hydrologist in charge of the Deer Creek Mine.

The permittee has submitted the water monitoring data for second quarter into the Electronic Water Database. Not all of the third quarter water monitoring data has been submitted into the Electronic Water Database, but is in process. The permittee said all of the information will be entered by the end of the third quarter. The fourth quarter water samples are in the process of being taken. The permittee said all samples will be taken by the end of the fourth quarter.

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

The mine site sediment pond has exceeded the total suspended solids standard for the daily average for one month in the third quarter. The requirement is not to exceed 25 mg per daily average. The sample taken was 30 mg per daily average. This information was submitted to Dept. of Water Quality.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The refuse piles were inspected by the permittee for third quarter and the report was P.E. certified. The Waste Rock Disposal Site and Elk Canyon were inspected on September 6, 2001.

8. NONCOAL WASTE

The mine site was generally free of non-coal waste material.

The permittee is in the process of evaluating the relocation of the non-coal waste storage site at the Deer Creek Mine. Wind blowing through the canyon has caused problems controlling the non-coal waste material. The permittee is hoping the relocation and a new design will eliminate this problem.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

No new surface facilities have been built since the last inspection.

21. BONDING AND INSURANCE

Reclamation agreement is dated December 11, 2000. The bonding amount is \$3,000,000.

Inspector's Signature:

Stephen I Deworzak #39

Date: November 15, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM

Chuck Semborski, PacifiCorp

Price Field office

O:\015018.DER\Compliance\2001\c_1107.wpd